



Existing Conditions



Future Conditions

Summary of Visual Changes

Type/Sensitivity of Users: Primarily local highway travelers with moderate sensitivity for visual quality
Volume of Users: Moderate
T/L Distance from Viewer: Middleground - approximately one-half mile
T/L Prominence in Landscape: Low - backdropped by mountain range and lower in landscape position
Existing Modifications: Gravel extraction pile, wood pole distribution line and rest area structures

Contrast Rating: Moderate
VRM Class: IV
Visual Impact Rating: Low

KOP 11
Highway 306

Figure 3.9-12

Falcon to Gonder Project EIS